MVSU01 and All kits for the MC88s CAM

Springs for the MC88s CAM do not require 0.5mm shim at base of spring Please remove and discard.

